

Section II
Soil and Site Information

Building Site Development
Stanley County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Local roads and streets		Shallow excavations		Lawns and landscaping	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
AgA: Agar-----	90	Very limited Low strength Shrink-swell Frost action	1.00 0.50 0.50	Somewhat limited Cutbanks cave	0.10	Not limited	
AgB: Agar-----	90	Very limited Low strength Shrink-swell Frost action	1.00 0.50 0.50	Somewhat limited Cutbanks cave	0.10	Not limited	
AkA: Fairlo-----	90	Very limited Low strength Shrink-swell Frost action	1.00 0.50 0.50	Somewhat limited Too clayey Cutbanks cave	0.12 0.10	Not limited	
AkB: Fairlo-----	90	Very limited Low strength Shrink-swell Frost action	1.00 0.50 0.50	Somewhat limited Too clayey Cutbanks cave	0.12 0.10	Not limited	
CaA: Canning-----	90	Somewhat limited Shrink-swell Low strength	0.50 0.22	Very limited Cutbanks cave	1.00	Not limited	
CaB: Canning-----	90	Somewhat limited Shrink-swell Low strength	0.50 0.22	Very limited Cutbanks cave	1.00	Not limited	
CaC: Canning-----	85	Somewhat limited Shrink-swell Low strength	0.50 0.22	Very limited Cutbanks cave	1.00	Not limited	
Cc: Carter-----	55	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Too clayey Cutbanks cave	1.00 0.10	Not limited	

Section II
Soil and Site Information

Building Site Development
Stanley County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Local roads and streets		Shallow excavations		Lawns and landscaping	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Capa-----	35	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Too clayey Depth to saturated zone Cutbanks cave	1.00 0.47 0.10	Very limited Sodium content	1.00
ChB: Chantier-----	90	Very limited Shrink-swell Depth to soft bedrock Low strength	1.00 1.00 1.00	Very limited Depth to soft bedrock Too clayey Cutbanks cave	1.00 1.00 0.10	Very limited Too clayey Depth to bedrock Droughty	1.00 1.00 1.00
CsC: Chantier-----	50	Very limited Shrink-swell Depth to soft bedrock Low strength	1.00 1.00 1.00	Very limited Depth to soft bedrock Too clayey Cutbanks cave	1.00 1.00 0.10	Very limited Too clayey Depth to bedrock Droughty	1.00 1.00 1.00
Sansarc-----	40	Very limited Shrink-swell Depth to soft bedrock Low strength Slope	1.00 1.00 1.00 0.63	Very limited Depth to soft bedrock Too clayey Slope Cutbanks cave	1.00 1.00 0.63 0.10	Very limited Too clayey Depth to bedrock Droughty Slope	1.00 1.00 1.00 0.63
CwB: Chantier-----	50	Very limited Shrink-swell Depth to soft bedrock Low strength	1.00 1.00 1.00	Very limited Depth to soft bedrock Too clayey Cutbanks cave	1.00 1.00 0.10	Very limited Too clayey Depth to bedrock Droughty	1.00 1.00 1.00
Bullcreek-----	40	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Too clayey Cutbanks cave	1.00 1.00	Very limited Too clayey Sodium content	1.00 1.00
Do: Dorna-----	95	Very limited Shrink-swell Low strength Frost action	1.00 1.00 0.50	Somewhat limited Too clayey Cutbanks cave	0.28 0.10	Not limited	

Section II
Soil and Site Information

Building Site Development
Stanley County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Local roads and streets		Shallow excavations		Lawns and landscaping	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Ho: Hoven-----	95	Very limited Shrink-swell Depth to saturated zone Low strength Ponding Frost action	1.00 1.00 1.00 1.00 0.50	Very limited Depth to saturated zone Ponding Too clayey Cutbanks cave	1.00 1.00 0.28 0.10	Very limited Depth to saturated zone Sodium content Ponding	1.00 1.00 1.00
HrA: Capa-----	85	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Too clayey Depth to saturated zone Cutbanks cave	1.00 0.47 0.10	Very limited Sodium content	1.00
Hs: Capa-----	50	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Too clayey Depth to saturated zone Cutbanks cave	1.00 0.47 0.10	Very limited Sodium content	1.00
Slickspots, Dry----	40	Not rated		Not rated		Not rated	
In: Inavale-----	90	Somewhat limited Flooding	0.40	Very limited Cutbanks cave	1.00	Somewhat limited Droughty	0.34
KeA: Kirley-----	90	Very limited Shrink-swell Low strength	1.00 1.00	Somewhat limited Cutbanks cave Too clayey	0.10 0.03	Not limited	
KeB: Kirley-----	90	Very limited Shrink-swell Low strength	1.00 1.00	Somewhat limited Cutbanks cave Too clayey	0.10 0.03	Not limited	

Section II
Soil and Site Information

Building Site Development
Stanley County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Local roads and streets		Shallow excavations		Lawns and landscaping	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Ko: Kolls-----	90	Very limited Shrink-swell Low strength Depth to saturated zone Ponding Frost action	1.00 1.00 1.00 1.00 0.50	Very limited Depth to saturated zone Too clayey Cutbanks cave Ponding	1.00 1.00 1.00 1.00	Very limited Too clayey Depth to saturated zone Ponding	1.00 1.00 1.00
LaB: Lakoma-----	95	Very limited Shrink-swell Low strength	1.00 1.00	Somewhat limited Too clayey Depth to soft bedrock Cutbanks cave	0.72 0.42 0.10	Very limited Too clayey Droughty Depth to bedrock	1.00 0.56 0.42
LaC: Lakoma-----	90	Very limited Shrink-swell Low strength	1.00 1.00	Somewhat limited Too clayey Depth to soft bedrock Cutbanks cave	0.72 0.42 0.10	Very limited Too clayey Droughty Depth to bedrock	1.00 0.56 0.42
LkD: Lakoma-----	45	Very limited Shrink-swell Low strength	1.00 1.00	Somewhat limited Too clayey Depth to soft bedrock Cutbanks cave	0.72 0.42 0.10	Very limited Too clayey Droughty Depth to bedrock	1.00 0.56 0.42
Okaton-----	40	Very limited Shrink-swell Depth to soft bedrock Low strength Slope	1.00 1.00 1.00 0.63	Very limited Depth to soft bedrock Too clayey Slope Cutbanks cave	1.00 0.72 0.63 0.10	Very limited Too clayey Depth to bedrock Droughty Slope	1.00 1.00 1.00 0.63
LoA: Lowry-----	95	Somewhat limited Low strength Frost action	0.78 0.50	Somewhat limited Cutbanks cave	0.10	Not limited	

Section II
Soil and Site Information

Building Site Development
Stanley County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Local roads and streets		Shallow excavations		Lawns and landscaping	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
LOB: Lowry-----	98	Somewhat limited Low strength Frost action	0.78 0.50	Somewhat limited Cutbanks cave	0.10	Not limited	
LoC: Lowry-----	99	Somewhat limited Low strength Frost action	0.78 0.50	Somewhat limited Cutbanks cave	0.10	Not limited	
McA: Mcclure-----	85	Very limited Shrink-swell Low strength	1.00 1.00	Somewhat limited Too clayey Cutbanks cave	0.72 0.10	Not limited	
McB: Mcclure-----	85	Very limited Shrink-swell Low strength	1.00 1.00	Somewhat limited Too clayey Cutbanks cave	0.72 0.10	Not limited	
MdA: Millboro-----	75	Very limited Shrink-swell Low strength	1.00 1.00	Somewhat limited Too clayey Cutbanks cave	0.72 0.10	Not limited	
MdB: Millboro-----	80	Very limited Shrink-swell Low strength	1.00 1.00	Somewhat limited Too clayey Cutbanks cave	0.72 0.10	Not limited	
MoA: Millboro-----	85	Very limited Shrink-swell Low strength	1.00 1.00	Somewhat limited Too clayey Cutbanks cave	0.72 0.10	Not limited	
MoB: Millboro-----	85	Very limited Shrink-swell Low strength	1.00 1.00	Somewhat limited Too clayey Cutbanks cave	0.72 0.10	Not limited	
Mu: Munjor-----	55	Somewhat limited Flooding	0.40	Somewhat limited Cutbanks cave	0.10	Not limited	
Inavale-----	35	Somewhat limited Flooding	0.40	Very limited Cutbanks cave	1.00	Somewhat limited Droughty	0.34

Section II
Soil and Site Information

Building Site Development
Stanley County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Local roads and streets		Shallow excavations		Lawns and landscaping	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Nb: Nimbro-----	90	Very limited Low strength Shrink-swell Frost action Flooding	1.00 0.50 0.50 0.40	Somewhat limited Cutbanks cave	0.10	Not limited	
OA: Orthents, Loamy-----	100	Very limited Slope Low strength Shrink-swell Frost action	1.00 0.78 0.50 0.50	Very limited Slope Cutbanks cave	1.00 0.10	Very limited Slope	1.00
OkE: Okaton-----	65	Very limited Shrink-swell Slope Depth to soft bedrock Low strength	1.00 1.00 1.00 1.00	Very limited Depth to soft bedrock Slope Too clayey Cutbanks cave	1.00 1.00 0.72 0.10	Very limited Too clayey Depth to bedrock Slope Droughty	1.00 1.00 1.00 1.00
Lakoma-----	25	Very limited Shrink-swell Slope Low strength	1.00 1.00 1.00	Very limited Slope Too clayey Depth to soft bedrock Cutbanks cave	1.00 0.72 0.42 0.10	Very limited Too clayey Slope Droughty Depth to bedrock	1.00 1.00 0.56 0.42
Bullcreek-----	3	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Too clayey Cutbanks cave	1.00 1.00	Very limited Too clayey Sodium content	1.00 1.00
OpA: Opal-----	95	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Cutbanks cave Too clayey Depth to soft bedrock	1.00 0.88 0.42	Very limited Too clayey Depth to bedrock Droughty	1.00 0.42 0.26
OpB: Opal-----	95	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Cutbanks cave Too clayey Depth to soft bedrock	1.00 0.88 0.42	Very limited Too clayey Depth to bedrock Droughty	1.00 0.42 0.26

Section II
Soil and Site Information

Building Site Development
Stanley County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Local roads and streets		Shallow excavations		Lawns and landscaping	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
OpC: Opal-----	90	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Cutbanks cave Too clayey Depth to soft bedrock	1.00 0.88 0.42	Very limited Too clayey Depth to bedrock Droughty	1.00 0.42 0.26
OtB: Opal-----	60	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Cutbanks cave Too clayey Depth to soft bedrock	1.00 0.88 0.42	Very limited Too clayey Depth to bedrock Droughty	1.00 0.42 0.26
Chantier-----	30	Very limited Shrink-swell Depth to soft bedrock Low strength	1.00 1.00 1.00	Very limited Depth to soft bedrock Too clayey Cutbanks cave	1.00 1.00 0.10	Very limited Too clayey Depth to bedrock Droughty	1.00 1.00 1.00
OtC: Opal-----	60	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Cutbanks cave Too clayey Depth to soft bedrock	1.00 0.88 0.42	Very limited Too clayey Depth to bedrock Droughty	1.00 0.42 0.26
Chantier-----	30	Very limited Shrink-swell Depth to soft bedrock Low strength	1.00 1.00 1.00	Very limited Depth to soft bedrock Too clayey Cutbanks cave	1.00 1.00 0.10	Very limited Too clayey Depth to bedrock Droughty	1.00 1.00 1.00
OxB: Opal-----	50	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Cutbanks cave Too clayey Depth to soft bedrock	1.00 0.88 0.42	Very limited Too clayey Depth to bedrock Droughty	1.00 0.42 0.26
Promise-----	40	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Too clayey Cutbanks cave	1.00 1.00	Very limited Too clayey	1.00

Section II
Soil and Site Information

Building Site Development
Stanley County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Local roads and streets		Shallow excavations		Lawns and landscaping	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Pg: Orthents, Gravelly--	99	Very limited Slope	1.00	Very limited Cutbanks cave Slope	1.00 1.00	Very limited Slope Droughty Gravel content	1.00 0.42 0.25
PrA: Promise-----	90	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Too clayey Cutbanks cave	1.00 1.00	Very limited Too clayey	1.00
PrB: Promise-----	95	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Too clayey Cutbanks cave	1.00 1.00	Very limited Too clayey	1.00
PrC: Promise-----	95	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Too clayey Cutbanks cave	1.00 1.00	Very limited Too clayey	1.00
Ps: Promise-----	68	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Too clayey Cutbanks cave	1.00 1.00	Very limited Too clayey	1.00
Capa-----	29	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Too clayey Depth to saturated zone Cutbanks cave	1.00 0.47 0.10	Very limited Sodium content	1.00
ReA: Ree-----	90	Very limited Low strength Shrink-swell Frost action	1.00 0.50 0.50	Somewhat limited Cutbanks cave	0.10	Not limited	
ReB: Ree-----	90	Very limited Low strength Shrink-swell Frost action	1.00 0.50 0.50	Somewhat limited Cutbanks cave	0.10	Not limited	

Section II
Soil and Site Information

Building Site Development
Stanley County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Local roads and streets		Shallow excavations		Lawns and landscaping	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
ReC: Ree-----	85	Very limited Low strength Shrink-swell Frost action	1.00 0.50 0.50	Somewhat limited Cutbanks cave	0.10	Not limited	
Rs: Rock Outcrop, Soft--	70	Not rated		Not rated		Not rated	
Sansarc-----	20	Very limited Shrink-swell Slope Depth to soft bedrock Low strength	1.00 1.00 1.00 1.00	Very limited Depth to soft bedrock Slope Too clayey Cutbanks cave	1.00 1.00 1.00 0.10	Very limited Too clayey Depth to bedrock Slope Droughty	1.00 1.00 1.00 1.00
SaE: Sansarc-----	85	Very limited Shrink-swell Slope Depth to soft bedrock Low strength	1.00 1.00 1.00 1.00	Very limited Depth to soft bedrock Slope Too clayey Cutbanks cave	1.00 1.00 1.00 0.10	Very limited Too clayey Depth to bedrock Slope Droughty	1.00 1.00 1.00 1.00
ScD: Sansarc-----	45	Very limited Shrink-swell Depth to soft bedrock Low strength Slope	1.00 1.00 1.00 0.63	Very limited Depth to soft bedrock Too clayey Slope Cutbanks cave	1.00 1.00 0.63 0.10	Very limited Too clayey Depth to bedrock Droughty Slope	1.00 1.00 1.00 0.63
Opal-----	40	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Cutbanks cave Too clayey Depth to soft bedrock	1.00 0.88 0.42	Very limited Too clayey Depth to bedrock Droughty	1.00 0.42 0.26

Section II
Soil and Site Information

Building Site Development
Stanley County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Local roads and streets		Shallow excavations		Lawns and landscaping	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
ScE: Sansarc-----	65	Very limited Shrink-swell	1.00	Very limited Depth to soft bedrock	1.00	Very limited Too clayey	1.00
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to soft bedrock	1.00	Too clayey	1.00	Slope	1.00
		Low strength	1.00	Cutbanks cave	0.10	Droughty	1.00
Opal-----	25	Very limited Shrink-swell	1.00	Very limited Slope	1.00	Very limited Too clayey	1.00
		Slope	1.00	Cutbanks cave	1.00	Slope	1.00
		Low strength	1.00	Too clayey	0.88	Depth to bedrock	0.42
				Depth to soft bedrock	0.42	Droughty	0.26
Sd: Sansarc-----	55	Very limited Shrink-swell	1.00	Very limited Depth to soft bedrock	1.00	Very limited Too clayey	1.00
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to soft bedrock	1.00	Too clayey	1.00	Slope	1.00
		Low strength	1.00	Cutbanks cave	0.10	Droughty	1.00
Rock Outcrop, Soft--	35	Not rated		Not rated		Not rated	
ShE: Schamber-----	85	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
				Cutbanks cave	1.00	Droughty	1.00
						Gravel content	0.38
SmD: Murdo-----	45	Not limited		Very limited Cutbanks cave	1.00	Somewhat limited Droughty	0.43
Schamber-----	45	Somewhat limited Slope	0.63	Very limited Cutbanks cave	1.00	Very limited Droughty	1.00
				Slope	0.63	Slope	0.63
						Gravel content	0.38

Section II
Soil and Site Information

Building Site Development
Stanley County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Local roads and streets		Shallow excavations		Lawns and landscaping	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
SmE: Schamber-----	50	Very limited Slope	1.00	Very limited Slope Cutbanks cave	1.00 1.00	Very limited Slope Droughty Gravel content	1.00 1.00 0.38
Murdo-----	40	Very limited Slope	1.00	Very limited Slope Cutbanks cave	1.00 1.00	Very limited Slope Droughty	1.00 0.43
Sp: Spillway-----	100	Very limited Depth to soft bedrock Low strength Slope	1.00 1.00 1.00	Very limited Depth to soft bedrock Slope Cutbanks cave	1.00 1.00 0.10	Very limited Depth to bedrock Droughty Slope	1.00 1.00 1.00
SuC: Sully-----	90	Somewhat limited Low strength Frost action	0.78 0.50	Somewhat limited Cutbanks cave	0.10	Not limited	
SuE: Sully-----	90	Very limited Slope Low strength Frost action	1.00 0.78 0.50	Very limited Slope Cutbanks cave	1.00 0.10	Very limited Slope	1.00
SvE: Sully-----	55	Very limited Slope Low strength Frost action	1.00 0.78 0.50	Very limited Slope Cutbanks cave	1.00 0.10	Very limited Slope	1.00
Sansarc-----	40	Very limited Shrink-swell Slope Depth to soft bedrock Low strength	1.00 1.00 1.00 1.00	Very limited Depth to soft bedrock Slope Too clayey Cutbanks cave	1.00 1.00 1.00 0.10	Very limited Too clayey Depth to bedrock Slope Droughty	1.00 1.00 1.00 1.00
Sw: Bullcreek-----	85	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Too clayey Cutbanks cave	1.00 1.00	Very limited Too clayey Sodium content	1.00 1.00

Section II
Soil and Site Information

Building Site Development
Stanley County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Local roads and streets		Shallow excavations		Lawns and landscaping	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Sx: Bullcreek-----	60	Very limited Shrink-swell Low strength	1.00 1.00	Very limited Too clayey Cutbanks cave	1.00 1.00	Very limited Too clayey Sodium content	1.00 1.00
Slickspots, Dry-----	30	Not rated		Not rated		Not rated	
W: Water (less Than 40 Acres)-----	100	Not rated		Not rated		Not rated	
Wc: Wendte-----	85	Very limited Shrink-swell Low strength Flooding	1.00 1.00 0.40	Somewhat limited Too clayey Depth to saturated zone Cutbanks cave	0.50 0.47 0.10	Very limited Too clayey	1.00
Wd: Wendte-----	90	Very limited Shrink-swell Flooding Low strength	1.00 1.00 1.00	Somewhat limited Flooding Too clayey Depth to saturated zone Cutbanks cave	0.80 0.50 0.47 0.10	Very limited Flooding Too clayey	1.00 1.00
Wf: Albaton-----	90	Very limited Shrink-swell Depth to saturated zone Frost action Flooding Low strength	1.00 1.00 1.00 1.00 1.00	Very limited Depth to saturated zone Ponding Flooding Too clayey Cutbanks cave	1.00 1.00 0.80 0.72 0.10	Very limited Too clayey Flooding Depth to saturated zone Ponding	1.00 1.00 1.00 1.00
WSE: Westover-----	85	Very limited Slope Frost action	1.00 0.50	Very limited Slope Cutbanks cave	1.00 1.00	Very limited Slope	1.00

Section II
Soil and Site Information

Building Site Development
Stanley County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Local roads and streets		Shallow excavations		Lawns and landscaping	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Wt: Witten-----	90	Very limited Shrink-swell Low strength Frost action	1.00 1.00 0.50	Somewhat limited Too clayey Depth to saturated zone Cutbanks cave	0.88 0.47 0.10	Very limited Too clayey	1.00